



RESULTS STORY

Enhancing Safety in Brazil



Real Results!

Enhancing Safety In Brazil

The primary responsibility of REACH Group Performance Coaches in Brazil is to aid in achieving Best of the Best operational performance while drilling in deepwater. The REACH Coaches are constantly looking for ways to ADD VALUE in other area's.

The REACH Coaches noticed that the Safety Representatives were having difficulty getting their safety messages across to the crew. The REACH Coaches offered their help and expertise.

The Reach Group Coach suggested that the rigs Safety Representative begin photo documenting HSE "Walkabouts" on a daily basis. Thus allowing a picture to speak a thousand words. The Rigs Safety Representatives were coached in techniques that will allow them to engage crew members in a non-defensive conversation. Allowing for an open line of communication were both parties are getting value from the safety information being discussed.

This type of in-depth walk-about also affords the crew the opportunity to see the safety representative and ask questions. It also allows the Safety Representative the opportunity to engage the crew in a positive and proactive way.

In the photo to the right we see the Safety Representative using the new skills he has learned to coach a welder and fire watch on the need for having a proper fire watch equipment set when welding operations are underway. This type of one on one approach works well in getting a commitment to safety from the people on the location performing the jobs.

